Hardware Information

Computer Vendor: Apple Inc., Model: MacBookPro5,5, Serial W89451B366J

Motherboard Vendor: Apple Inc., Model: Mac-F2268AC8

Processor Intel(R) Core(TM)2 Duo CPU P8700 @ 2.53GHz

RAM 8192 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 64:b9:e8:d1:fc:74
NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 00:26:bb:10:e6:cc

DVD writer DVD-R UJ-868

Drive 1 Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

110108PBL200NSJ5BWNV, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 9, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 9422FFF3-9BEA-466F-9263-432ADFE3A26C

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 583084

Lot Name Geometry Global

Lot Number 19117 "Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

110108PBL200NSJ5BWNV, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 1CB5F25C-89B6-4496-B1A3-22D650600EE9

Action Start Time Monday, 01 Jan 2001 at 00:31:09

Action Duration 01:12:51

Remapped sectors 1
Dirty Sectors 0

Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	488397168
Sectors Not Overwritten	0
Sectors Verified	48839717
NIST Method Type	Purge

