

Hardware Information

Computer Vendor: Hewlett-Packard, Model: HP ProBook 6360b, Serial 2CE1240G1K

Motherboard Vendor: Hewlett-Packard, Model: 1621

Processor Intel(R) Core(TM) i5-2410M CPU @ 2.30GHz

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Intel Corporation, 82579V Gigabit Network Connection, MAC address:

b4:99:ba:56:2f:0a

NIC Broadcom Inc. and subsidiaries, BCM43224 802.11a/b/g/n, MAC address:

ac:81:12:60:2f:f7

DVD-RAM writer DVD RW AD-7711H

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 51IWB3XZB,

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

Definition Audio Controller

USB Ports: 2, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID D2AB3842-9A7B-49BF-A12B-CEC542F02966

User name ITAMG Computer ID Unavailable

User fields

Username Randy Prashad

Asset Number 582677

Lot Name Family Residences & Essential Enterprises, Inc

Lot Number 19172 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

51IWB3XZB, Size: 320.07 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 6486BE6A-49D9-43F0-AE13-4EBF84230524

Action Start Time Tuesday, 01 Jan 1980 at 00:14:34

Action Duration	01:02:15
Remapped sectors	0
Dirty Sectors	0
Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Sectors Overwritten	625142448
Sectors Not Overwritten	0
Sectors Verified	62514245
NIST Method Type	Clear