



CERTIFIED REPORT

Hardware Information

Vendor: Hewlett-Packard, Model: HP ProBook 4530s, Serial CNU2061KBB Computer

Motherboard Vendor: Hewlett-Packard, Model: 167C

Intel(R) Core(TM) i3-2330M CPU @ 2.20GHz Processor

4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM **RAM**

Realtek Semiconductor Co., Ltd., RTL8188CE 802.11b/g/n WiFi Adapter, NIC

MAC address: Unavailable

NIC Realtek Semiconductor Co., Ltd., RTL8111/8168/8411 PCI Express Gigabit

Ethernet Controller, MAC address: e4:11:5b:3c:ba:0b

DVD-RAM writer **DVD-RAM UJ8B1**

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK5061GSYN, Serial: 121AFFA5S,

Size: 500.11 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

Definition Audio Controller

USB Ports USB Ports: 0, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard **Pass** Processor **Pass** Memory **Pass**

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 42C76521-5BAC-4D40-8279-6DB499CC273B

Job fields

Randy Prashad Username

572511 User2

User3 Northwell Health

User4 19086 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK5061GSYN, Serial:

121AFFA5S, Size: 500.11 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

24395C09-6DF0-45EE-8FB3-F9C53D3B5E41 **UUID**

Time started Wednesday, 05 Feb 2020 at 15:17:57

Duration 06:36:36

Remapped sectors 0

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Sectors overwritten	976773168
Sectors not overwritten	0
Sectors verified	976773168
NIST Method Type	Clear

