



CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E6330, Serial 2R6DYW1

Motherboard Vendor: Dell Inc., Model: 0P1XMK

Processor Intel(R) Core(TM) i5-3320M CPU @ 2.60GHz

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: b8:ca:3a:d7:d4:21

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

DVD-RAM writer DVD+-RW DU-8A5HH

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 23JCY25SF,

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics

Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High

Definition Audio Controller

USB Ports: 2, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 815508D6-A33D-4277-B404-61D980FC24CA

Job fields

Username Randy Prashad

User2 546897

User3 PRA Health Sciences

User4 18743 \"Product\" Computer

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

23JCY25SF, Size: 320.07 GB, Pre-wipe SMART health status: PASSED,

Post-wipe SMART health status: PASSED

Action Result FAILURE

UUID 4331BB22-EA81-4CBA-BFE2-4E20EF8F1381

Time started Thursday, 05 Dec 2019 at 14:58:07

Duration 04:30:37

Remapped sectors 0

Dirty Sectors	15761
Drive Errors Detected	124
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Unknown

