Hardware Information

Computer Vendor: Apple Inc., Model: iMac9,1, Serial QP9310UB0TJ

Motherboard Vendor: Apple Inc., Model: Mac-F2218FA9

Processor Intel(R) Core(TM)2 Duo CPU E8135 @ 2.66GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 00:26:4a:01:da:84 NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 00:26:08:f0:5a:1a

DVD writer DVD RW AD-5670S

Drive 1 Vendor: Hitachi, Model: Hitachi HDT721064SLA360, Serial:

STFD08MG1M0SZK, Size: 640.14 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 10, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 1DF71170-54C8-435E-802C-F51FF6149CFF

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 548359
Lot Name 18658
Lot Number 18658
\"Product\" All_In_One

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HDT721064SLA360, Serial:

STFD08MG1M0SZK, Size: 640.14 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 41A11082-01E9-43E8-9188-67C94F3D7F29

Action Start Time Thursday, 09 Jan 2020 at 22:20:32

Action Duration 02:13:33

Remapped sectors 0
Dirty Sectors 0

Drive Errors Detected 0
DCO Found / Removed No / No
HPA Found / Removed No / No
AMAX Found / Removed No / No
Sectors Overwritten 1250263728
Sectors Not Overwritten 0
Sectors Verified 125026373
NIST Method Type Clear

