



CERTIFIED REPORT

Hardware Information

Computer Vendor: FUJITSU, Model: LIFEBOOK T902, Serial Q4605727

Motherboard Vendor: FUJITSU, Model: FJNB25E

Processor Intel(R) Core(TM) i5-3340M CPU @ 2.70GHz

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: 74:2b:62:f8:64:f3

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

DVD-RAM writer DVD-RAM UJ8E2

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3276GSX, Serial: 934JC605T, Size:

320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe SMART

health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics

Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High

Definition Audio Controller

USB Ports: 5, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 4A57EF01-EC8E-4F4E-A20C-07D24C7A420B

Job fields

Username Randy Prashad

User2 558498

User3 Northwell Health

User4 18993 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3276GSX, Serial: 934JC605T,

Size: 320.07 GB , Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Action Result SUCCESS

DCO-Locked WARNING: Drive has DCO features but they have been locked out prior to

WipeDrive running.

UUID 7CB85C86-3210-4452-95F0-977F7BDF7ABE

Time started Thursday, 06 Feb 2020 at 09:36:14

Duration	05:16:12
Remapped sectors	0
Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Unknown