



CERTIFIED REPORT

Hardware Information

Computer Vendor: IBM, Model: IBM System x -[794772U]-, Serial 99F2248

Motherboard Vendor: IBM, Model: 59Y3827

Processor Intel(R) Xeon(R) CPU X5550 @ 2.67GHz
Processor Intel(R) Xeon(R) CPU X5550 @ 2.67GHz

RAM 26624 MB, Memory banks filled Unavailable/7, Other DIMM

NIC Broadcom Limited, NetXtreme II BCM5709 Gigabit Ethernet, MAC address:

00:21:5e:dd:1b:04

NIC Broadcom Limited, NetXtreme II BCM5709 Gigabit Ethernet, MAC address:

00:21:5e:dd:1b:06

NIC Unavailable, Unavailable, MAC address: 02:21:5e:df:9b:07

DVD reader RW/DVD GCC-T20N

Drive 1 Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0K01F00009012BGM2, Size: 73.41 GB

Drive 2 Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0JQT000009012QXL1, Size: 73.41 GB

Display Adapter Vendor: Matrox Electronics Systems Ltd., Model: MGA G200EV

USB Ports: 5, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 4B42AF5F-A1C0-4E5A-AC87-C6BE71CF2B70

Job fields

Username Randy Prashad

User2 571423

User3 Northwell Health

User4 18978 \"Product\" Server

Target Drive 1 - Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0K01F00009012BGM2, Size: 73.41 GB

Action Result FAILURE

UUID CB1330BC-3D4A-4904-A21D-BAB3E86531D1

Time started Wednesday, 29 Jan 2020 at 11:31:25

Duration 00:28:18

Remapped sectors 478
Dirty Sectors 0

Drive Errors Detected DCO found / removed No / No HPA found / removed No / No AMAX found / removed No / No Sectors overwritten 143374000 Sectors not overwritten Sectors verified 2048 **NIST Method Type** Unknown

2 - Vendor: IBM-ESXS, Model: ST973452SS, Serial: **Target Drive**

3TA0JQT000009012QXL1, Size: 73.41 GB

SUCCESS Action Result

UUID 10875218-B6FD-48CD-9056-B0B2EDAB1496

Time started Wednesday, 29 Jan 2020 at 11:31:26

Duration 00:38:48 Remapped sectors 181 **Dirty Sectors** 0 **Drive Errors Detected** 0 DCO found / removed No / No HPA found / removed No / No AMAX found / removed No / No

143374000 Sectors not overwritten 0

Sectors overwritten

Sectors verified 143374000

NIST Method Type Clear