

Operation Info

Wipe Method	NIST 800-88r1 (recommended)	Action Start Time	Wednesday, 13 May 2020 at 11:37:00		
Action Result	SUCCESS	Action Duration	01:30:07		
Target Drive	Vendor: Hitachi	Dirty Sectors	0		
	Model: Hitachi HDS721050CLA360	Drive Errors	0		
	Serial: JP1572FL129URK	DCO Found / Removed	No / No		
	Size: 500.11 GB	DCO Locked	Yes		
	Pre-wipe SMART Health Status: PASSED	HPA Found / Removed	No / No		
Software Used	WipeDrive Enterprise 9.3.2.1 64-bit	AMAX Found / Removed	No / No		
Kernel Version	5.2.11-mac	Secure Erase Passes	1		
Job UUID	B5446DB5-7F04-4487-BD6D-A5764956CE40	Sectors Overwritten	976773168		
User Fields	Username: Randy Prashad	Sectors Not Overwritten	0		
	User2: 578105	Sectors Verified	97677317		
	User3: Avis Budget Group	NIST Method Type	Unknown		
	User4: 19134				
UUID	CDC8DF16-7582-4655-83A3-E0807FF8CD43				

Hardware Information

Computer	Vendor: LENOVO	Display Adapter	Vendor: Intel Corporation		
	Model: 3598A7U		Model: 2nd Generation Core Processor Family Integrated		
	Serial: MJVRNZF		Graphics Controller		
Motherboard	Vendor: LENOVO	Multimedia Adapter	Vendor: Intel Corporation		
	Model:		Model: 6 Series/C200 Series Chipset Family High		
Processor	Intel(R) Core(TM) i3-2120 CPU @ 3.30GHz		Definition Audio Controller		
RAM	4096 MB, Memory banks filled 1/2, DDR3 DIMM	USB Ports	USB Ports: 2		
NIC	Realtek Semiconductor Co., Ltd., RTL8111/8168/8411		USB2 Ports: 2		
	PCI Express Gigabit Ethernet Controller		USB3 Ports: 0		
	MAC Address: d4:3d:7e:38:fe:85				
DVD-RAM writer	DVD-RW DH16ACSH				

Model: Hitachi HDS721050CLA360 Serial: JP1572FL129URK Size: 500.11 GB Drive Media Type: Platter

Vendor: Hitachi

Drive Media Type: Platter Firmware Version: JP2OA50E

Pre-wipe SMART health status: PASSED

Hardware Test Overview

Drive 1

Processor	Pass	Display	Not Enabled	Mouse	Not Enabled	Keyboard	Not Enabled
Network	Not Enabled	Storage	Pass	Memory	Pass	Web Camera	Not Enabled
Sound	Not Enabled						