Hardware Information

Computer Vendor: Apple Inc., Model: MacBookPro7,1, Serial W80490XYATQ

Motherboard Vendor: Apple Inc., Model: Mac-F222BEC8

Processor Intel(R) Core(TM)2 Duo CPU P8800 @ 2.66GHz

RAM 8192 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC Broadcom Inc. and subsidiaries. BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: f0:b4:79:22:52:a5

NIC Broadcom Inc. and subsidiaries, NetXtreme BCM5764M Gigabit Ethernet

PCIe, MAC address: 10:9a:dd:53:f6:8a

DVD writer DVD-R UJ-898

Drive 1 Vendor: Hitachi, Model: Hitachi HTS545032B9SA02, Serial:

101112PBSC00PYG32GTS, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: MCP89 [GeForce 320M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP89 High Definition Audio

USB Ports: 10, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 5FCC22A7-D950-49B8-BD1D-4E6A638DF3C5

User name ITAMG
Computer ID Not Specified

User fields

Username Randy Prashad

Asset Number 583078

Lot Name Geometry Global

Lot Number 19117

"Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS545032B9SA02, Serial:

101112PBSC00PYG32GTS, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 4EB91421-04A4-40C5-AE3A-7CF11D6041B4

Action Start Time Monday, 01 Jan 2001 at 00:03:15

Action Duration 01:49:21

Remapped sectors (

Dirty Sectors	0
Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	625142448
Sectors Not Overwritten	0
Sectors Verified	62514245
NIST Method Type	Purge