



## CERTIFIED REPORT

**Hardware Information** 

Computer Vendor: Apple Inc., Model: MacBookPro9,2, Serial C02JH8VZDTY3

Motherboard Vendor: Apple Inc., Model: Mac-6F01561E16C75D06

Processor Intel(R) Core(TM) i5-3210M CPU @ 2.50GHz

RAM 8192 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Broadcom Limited, NetXtreme BCM57765 Gigabit Ethernet PCIe, MAC

address: a8:20:66:2c:51:66

NIC Broadcom Limited, BCM4331 802.11a/b/g/n, MAC address: Unavailable

DVD writer DVD-R UJ-8A8

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK5065GSXF, Serial: 12I5PGP9T,

Size: 500.11 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics

Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High

**Definition Audio Controller** 

USB Ports: 6, USB2 Ports: 2, USB3 Ports: 1

Thunderbolt ports: 1, Thunderbolt 2 ports: 0, Thunderbolt 3 ports: 0

**Hardware Tests** 

Motherboard Pass
Processor Pass
Memory Pass

**Wipe Information** 

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 32B9FAF6-7C68-430A-98D5-B04FE25BDDF9

Job fields

Username Randy Prashad

User2 568035

User4 18890 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK5065GSXF, Serial:

12I5PGP9T, Size: 500.11 GB, Pre-wipe SMART health status: PASSED,

Post-wipe SMART health status: PASSED

Action Result FAILURE

UUID 32D795FC-05A5-44A4-BA6B-5DF29E06DB47

Time started Sunday, 06 Jan 2019 at 04:26:52

Duration 02:36:27 Remapped sectors 13

Dirty Sectors	0
Drive Errors Detected	2
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	976773168
Sectors not overwritten	0
Sectors verified	97677317
NIST Method Type	Unknown

