## Hardware Information

Computer Vendor: Apple Inc., Model: MacBookPro5,1, Serial W88506V51GA

Motherboard Vendor: Apple Inc., Model: Mac-F42D86C8

Processor Intel(R) Core(TM)2 Duo CPU T9400 @ 2.53GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 00:23:32:d3:31:f6
NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 00:23:6c:8f:30:a8

DVD writer DVD-R UJ-868

Drive 1 Vendor: Hitachi, Model: Hitachi HTS543232L9SA02, Serial:

081128FB1400LEJ7VARF, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: G96M [GeForce 9600M GT]

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 7, USB2 Ports: 2, USB3 Ports: 0

**Hardware Tests** 

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method DoD 5220,22-M - 3 Pass

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID B54FA4D6-6648-497C-9471-61F2EEE66E3C

User name ITAMG Computer ID Asset Tag#

**User fields** 

Username Randy Prashad

Asset Number 563365

Lot Name Metropolitan Museum of Art

Lot Number 19037 "Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS543232L9SA02, Serial:

081128FB1400LEJ7VARF, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 0BE960E0-BD91-4B49-9047-288B3265DCFD

Action Start Time Sunday, 12 Jan 2020 at 11:20:44

Action Duration 07:09:33

Remapped sectors

Dirty Sectors	0
Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	625142448
Sectors Not Overwritten	0
Sectors Verified	625142448
NIST Method Type	Clear