



CERTIFIED REPORT

Hardware Information

Computer Vendor: Microsoft Corporation, Model: Surface Laptop, Serial

004766573957

Motherboard Vendor: Microsoft Corporation, Model: Surface Laptop

Processor Intel(R) Core(TM) i5-7300U CPU @ 2.60GHz

RAM 8192 MB, Memory banks filled Unavailable/2, LPDDR3 Row Of Chips NIC Marvell Technology Group Ltd., 88W8897 [AVASTAR] 802.11ac Wireless,

MAC address: Unavailable

Drive 1 Vendor: 0x1179, Model: THNSN0256GTYA TOSHIBA, Serial:

67QY11CUYXEU, Size: 256.06 GB

Display Adapter Vendor: Intel Corporation, Model: HD Graphics 620

Multimedia Adapter Vendor: Intel Corporation, Model: Xeon E3-1200 v5/E3-1500 v5/6th Gen

Core Processor Imaging Unit

Multimedia Adapter Vendor: Intel Corporation, Model: Intel Corporation

Multimedia Adapter Vendor: Intel Corporation, Model: Sunrise Point-LP HD Audio

USB Ports: 0, USB2 Ports: 0, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3.2 64-bit

Kernel Version 4.16.15-gentoo

Job UUID 4FC4726D-E1AB-48CE-B9ED-EE5DAE976FF1

User name ITAMG

Computer ID <BAD INDEX>

User fields

Username Randy Prashad

Asset Number 566659

Lot Name RefurbConnect

Lot Number 19067 "Product\" Laptop

Target Drive 1 - Vendor: 0x1179, Model: THNSN0256GTYA TOSHIBA, Serial:

67QY11CUYXEU, Size: 256.06 GB

Action Result SUCCESS

UUID F3D2410D-79FE-472F-AA43-F1CBCDFF0432

Time started Tuesday, 07 Jan 2020 at 16:03:18

Duration 01:07:40

Dirty Sectors 0
Drive Errors Detected 0

DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Sectors overwritten	500118192
Sectors not overwritten	0
Sectors verified	50011820
NIST Method Type	Clear

