



## CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E5530 non-vPro, Serial 6128XW1

Motherboard Vendor: Dell Inc., Model: 05GRXT

Intel(R) Core(TM) i5-3210M CPU @ 2.50GHz Processor

4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM **RAM** 

Broadcom Limited, BCM43228 802.11a/b/g/n, MAC address: Unavailable NIC NIC Broadcom Limited, NetXtreme BCM5761 Gigabit Ethernet PCIe, MAC

address: b8:ca:3a:d3:08:3c

**DVD-RAM** writer DVD+-RW DS-8A9SH

Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 237PT79IT, Size: Drive 1

320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe SMART

health status: PASSED

Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics Display Adapter

Controller

Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High Multimedia Adapter

**Definition Audio Controller** 

**USB Ports** USB Ports: 0, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard **Pass** Processor **Pass** Memory **Pass** 

**Wipe Information** 

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

3DD47DE8-8C28-48CB-9D28-44BC853AC827 Job UUID

Job fields

Username Randy Prashad

547965 User2

**Related Companies** User3

User4 17604 \"Product\" Laptop

**Target Drive** 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

237PT79IT, Size: 320.07 GB, Pre-wipe SMART health status: PASSED,

Post-wipe SMART health status: PASSED

**SUCCESS Action Result** 

**UUID** CF20C113-C1C2-4A7E-A2E8-A4051085DE90

Time started Wednesday, 22 Jan 2020 at 12:57:37

03:38:31 Duration

Remapped sectors 0 0 **Dirty Sectors** 

Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Clear

