



## CERTIFIED REPORT

Hardware Information

Vendor: Dell Inc., Model: Latitude E6320, Serial 83LWGV1 Computer

Motherboard Vendor: Dell Inc., Model: 05VMY6

Intel(R) Core(TM) i5-2520M CPU @ 2.50GH Processor

3072 MB, Memory banks filled Unavailable/2, DDR3 SODIMM **RAM** 

Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC NIC

address: d4:be:d9:53:c4:d1

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

**DVD-RAM** writer DVD+-RW UJ8B2

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 726HF3HLS,

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

**Definition Audio Controller** 

USB Ports: 0, USB2 Ports: 2, USB3 Ports: 0 **USB Ports** 

**Hardware Tests** 

Motherboard **Pass** Processor **Pass** Memory **Pass** 

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 4792BC6B-C3BC-49D1-A42D-FFC1C5662B98

Job fields

Randy Prashad Username

User2 567805

User3 Owens Corning

User4 19075 \"Product\" Laptop

**Target Drive** 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

726HF3HLS, Size: 320.07 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

**Action Result SUCCESS** 

**UUID** 7BFCF32D-0AD5-4E21-AF1F-8E81E1A4E491

Time started Monday, 24 Feb 2020 at 10:37:18

01:08:18 Duration

Remapped sectors 0

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	62514245
NIST Method Type	Purae

