



CERTIFIED REPORT

Hardware Information

Computer Vendor: IBM, Model: System x3650 M2 -[794772U]-, Serial 99F2251

Motherboard Vendor: IBM, Model: 59Y3827

Processor Intel(R) Xeon(R) CPU X5550 @ 2.67GHz
Processor Intel(R) Xeon(R) CPU X5550 @ 2.67GHz

RAM 32768 MB, Memory banks filled Unavailable/9, Other DIMM

NIC Broadcom Limited, NetXtreme II BCM5709 Gigabit Ethernet, MAC address:

00:21:5e:dd:1b:70

NIC Broadcom Limited, NetXtreme II BCM5709 Gigabit Ethernet, MAC address:

00:21:5e:dd:1b:72

NIC Unavailable, Unavailable, MAC address: 02:21:5e:df:9b:73

DVD reader RW/DVD GCC-T20N

Drive 1 Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0GMWC00009012R3C6, Size: 73.41 GB

Drive 2 Vendor: IBM-ESXS, Model: HUC156007CSS20, Serial: 0THWKP5P, Size:

73.41 GB

Display Adapter Vendor: Matrox Electronics Systems Ltd., Model: MGA G200EV

USB Ports: 5, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 2DB12335-ECFB-4A6A-A5CF-54151280B311

Job fields

Username Randy Prashad

User2 571400

User3 Northwell Health

User4 18978 \"Product\" Server

Target Drive 1 - Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0GMWC00009012R3C6, Size: 73.41 GB

Action Result SUCCESS

UUID BAFA977B-0158-4D68-B772-A9CBFC7F93AF

Time started Wednesday, 29 Jan 2020 at 13:26:19

Duration 00:37:27

Remapped sectors 50 Dirty Sectors 0

Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Sectors overwritten	143374000
Sectors not overwritten	0
Sectors verified	143374000
NIST Method Type	Clear

Target Drive 2 - Vendor: IBM-ESXS, Model: HUC156007CSS20, Serial: 0THWKP5P,

Size: 73.41 GB

Action Result SUCCESS **UUID** 5D79DD26-6DF1-418B-9B67-9C306901389D Time started Wednesday, 29 Jan 2020 at 13:26:17 Duration 00:46:21 Remapped sectors 0 0 **Dirty Sectors Drive Errors Detected** No / No DCO found / removed HPA found / removed No / No AMAX found / removed No / No

Sanitize Overwrite 1

Passes

Sectors overwritten 143374000

Sectors not overwritten 0

Sectors verified 143374000 NIST Method Type Clear