



CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E5530 non-vPro, Serial DN18XW1

Motherboard Vendor: Dell Inc., Model: 05GRXT

Intel(R) Core(TM) i5-3210M CPU @ 2.50GHz Processor

4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM **RAM**

Broadcom Limited, BCM43228 802.11a/b/g/n, MAC address: Unavailable NIC NIC

Broadcom Limited, NetXtreme BCM5761 Gigabit Ethernet PCIe, MAC

address: b8:ca:3a:d3:06:4a

DVD-RAM writer DVD+-RW DS-8A9SH

Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 237PT78TT, Drive 1

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics Display Adapter

Controller

Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High Multimedia Adapter

Definition Audio Controller

USB Ports USB Ports: 0, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard **Pass** Processor **Pass** Memory **Pass**

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

7E165D83-E77F-4410-A353-873B4CB3115A Job UUID

Job fields

Username Randy Prashad

547984 User2

Related Companies User3

User4 17604 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

237PT78TT, Size: 320.07 GB, Pre-wipe SMART health status: PASSED,

Post-wipe SMART health status: PASSED

FAILURE Action Result

UUID 3CB3D9B4-4C71-445A-AB28-2978B9CF94E3

Time started Wednesday, 22 Jan 2020 at 13:52:35

03:57:34 Duration

Remapped sectors 0

537 **Dirty Sectors**

Drive Errors Detected	4
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Unknown

