Hardware Information

Computer Vendor: Apple Inc., Model: MacBookPro5,5, Serial W89397GG66E

Motherboard Vendor: Apple Inc., Model: Mac-F2268AC8

Processor Intel(R) Core(TM)2 Duo CPU P8700 @ 2.53GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 00:26:bb:61:4c:44
NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 00:26:bb:0a:2f:5a

DVD writer DVDRW GS23N

Drive 1 Vendor: Fujitsu, Model: FUJITSU MJA2250BH FFS G1, Serial:

K94DT982AD7C, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 9, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 3D76A108-E9CD-4639-B075-392B5DE9A1B8

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 550799

Lot Name Metropolitan Museum of Art

Lot Number 17594 \"Product\" Laptop

Target Drive 1 - Vendor: Fujitsu, Model: FUJITSU MJA2250BH FFS G1, Serial:

K94DT982AD7C, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 47D57944-FB09-4891-BE30-3FFE87E1ED11

Action Start Time Monday, 01 Jan 2001 at 00:13:23

Action Duration 01:06:46

Remapped sectors 0
Dirty Sectors 0

Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Sectors Overwritten	488397168
Sectors Not Overwritten	0
Sectors Verified	48839717
NIST Method Type	Clear

