## **Hardware Information**

Computer Vendor: Apple Inc., Model: MacBookPro7,1, Serial W80321HZATP

Motherboard Vendor: Apple Inc., Model: Mac-F222BEC8

Processor Intel(R) Core(TM)2 Duo CPU P8600 @ 2.40GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC Broadcom Inc. and subsidiaries. BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 78:ca:39:b2:62:d1

NIC Broadcom Inc. and subsidiaries, NetXtreme BCM5764M Gigabit Ethernet

PCIe, MAC address: c4:2c:03:34:e2:ad

DVD writer DVD-R UJ-898

Drive 1 Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

100728PBL200CSHE172N, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: MCP89 [GeForce 320M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP89 High Definition Audio

USB Ports: 10, USB2 Ports: 2, USB3 Ports: 0

**Hardware Tests** 

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID AC1F0EBB-1767-4A5C-9335-8910BF93B031

User name ITAMG
Computer ID Not Specified

**User fields** 

Username Randy Prashad

Asset Number 583074

Lot Name Geometry Global

Lot Number 19117
"Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

100728PBL200CSHE172N, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 6BD934F9-D780-4B93-BAC4-F25E5000DE1C

Action Start Time Monday, 01 Jan 2001 at 01:30:05

Action Duration 01:16:09

Remapped sectors (

Dirty Sectors	0
Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	488397168
Sectors Not Overwritten	0
Sectors Verified	48839717
NIST Method Type	Purge