



CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E6330, Serial 2TKCXW1

Motherboard Vendor: Dell Inc., Model: 0P1XMK

Processor Intel(R) Core(TM) i5-3320M CPU @ 2.60GHz

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: b8:ca:3a:d3:e5:b8

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

DVD-RAM writer DVD+-RW UJ8C2

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 13CDYNMQF,

Size: 320.07 GB, Pre-wipe SMART health status: FAILED!, Post-wipe

SMART health status: FAILED!

Display Adapter Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics

Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High

Definition Audio Controller

USB Ports: 2, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 9DDDC0F1-9E98-4B17-BF33-C1521119A981

Job fields

Username Randy Prashad

User2 547079

User3 PRA Health Sciences

User4 18832 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

13CDYNMQF, Size: 320.07 GB, Pre-wipe SMART health status:

FAILED!, Post-wipe SMART health status: FAILED!

Action Result SUCCESS

UUID 4835B950-154B-4D43-92FC-1786E8B186DB

Time started Friday, 21 Aug 2015 at 17:38:21

Duration 09:23:14 Remapped sectors 1965

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Clear

