



## CERTIFIED REPORT

Hardware Information

Vendor: Hewlett-Packard, Model: HP EliteBook 2560p, Serial USH230A0C7 Computer

Motherboard Vendor: Hewlett-Packard, Model: 162B

Intel(R) Core(TM) i7-2620M CPU @ 2.70GHz Processor

**RAM** 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: 10:1f:74:e6:97:ac

NIC Broadcom Limited, BCM4313 802.11bgn Wireless Network Adapter, MAC

address: Unavailable

**DVD-RAM** writer **DVDRAM GU60N** 

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial: 22LVT7XMT,

Size: 250.06 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

**Definition Audio Controller** 

**USB Ports** USB Ports: 3, USB2 Ports: 2, USB3 Ports: 0

**Hardware Tests** 

Motherboard **Pass** Processor **Pass** Memory **Pass** 

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 7B64FCC5-B51F-47CE-9837-41AE393FA1D4

Job fields

Randy Prashad Username

User2 551032

User3 Virtua Health System

User4 17451 \"Product\" Laptop

**Target Drive** 1 - Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial:

22LVT7XMT, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

**Action Result SUCCESS** 

**UUID** 4E623D7A-A41B-4687-A19C-9E617CA60E39

Time started Tuesday, 01 Jan 1980 at 00:17:34

Duration 00:54:36

0 Remapped sectors

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Sectors overwritten	488397168
Sectors not overwritten	0
Sectors verified	48839717
NIST Method Type	Clear

