Riley Auto Repair

500 Shaw Walk
Pearland, TX
Phone 713-555-8121

Repair Estimate

Estimate number:	EST-384300
Estimate date:	2024-02-20
Customer:	Tricia Avery
Phone:	832-555-6152
Insurance claim:	C-1012
Vehicle:	2017 Hyundai Elantra
VIN:	WT5X2TE22F9KT4891
License plate:	258-UQG

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,375.26
Left quarter panel	1	$1,327.90
Front bumper cover	1	$1,551.69
Body labor	42.7 hrs	$2,904.06
Paint and materials		$1,741.92
TOTAL		$8,900.83