Brewer Collision Center

07991 Amanda Parkways Suite 251
Sugar Land, TX
Phone 832-555-4278

Repair Estimate

Estimate number:	EST-455885
Estimate date:	April 14, 2024
Customer:	Michael Long
Phone:	713-555-3237
Insurance claim:	C-1037
Vehicle:	2017 Hyundai Elantra
VIN:	SS5JJCS76KWA92590
License plate:	PJE-3330

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$944.25
Rear bumper cover	1	$1,138.24
Rear body panel	1	$601.32
Body labor	35.0 hrs	$2,377.85
Paint and materials		$933.14
TOTAL		$5,994.80