Lee Auto Repair

62473 Scott Wall Apt. 080
Pasadena, TX
Phone 281-555-2677

Repair Estimate

Estimate number:	EST-693326
Estimate date:	25 May 2025
Customer:	John Williams
Phone:	832-555-3356
Insurance claim:	C-1048
Vehicle:	2015 Chevrolet Malibu
VIN:	JXH7UBGY0719M5541
License plate:	

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$725.00
Rear bumper cover	1	$639.13
Left tail lamp assembly	1	$784.37
Body labor	26.4 hrs	$1,794.26
Paint and materials		$992.75
TOTAL		$4,935.51