Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-741556
Estimate date:	11 Mar 2024
Customer:	Donna Thomas
Phone:	832-555-0412
Insurance claim:	C-1067
Vehicle:	2020 Honda Civic
VIN:	5YPDS7Y23DTRL6171
License plate:	24-ZF02

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$925.32
Rear bumper reinforcement	1	$1,125.48
Trunk lid	1	$675.98
Body labor	33.3 hrs	$2,262.82
Paint and materials		$1,138.71
TOTAL		$6,128.31