Brewer Collision Center

07991 Amanda Parkways Suite 251
Sugar Land, TX
Phone 832-555-4278

Repair Estimate

Estimate number:	EST-278250
Estimate date:	July 5, 2024
Customer:	Ryan Palmer
Phone:	281-555-1027
Insurance claim:	C-1073
Vehicle:	2020 Honda Civic
VIN:	HUAK70W72BH2X1307
License plate:	OLI 1815

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,111.82
Rear body panel	1	$846.52
Rear bumper reinforcement	1	$491.41
Body labor	27.4 hrs	$1,863.76
Paint and materials		$1,081.68
TOTAL		$5,395.19