Riley Auto Repair

500 Shaw Walk
Pearland, TX
Phone 713-555-8121

Repair Estimate

Estimate number:	EST-643013
Estimate date:	2025-03-12
Customer:	Janet Sandoval
Phone:	713-555-7893
Insurance claim:	C-1095
Vehicle:	2011 Chevrolet Malibu
VIN:	JYYSNXJ76VLFU3146
License plate:	KOK 156

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,256.69
Trunk lid	1	$858.34
Rear bumper reinforcement	1	$653.14
Body labor	29.3 hrs	$1,990.51
Paint and materials		$1,144.05
TOTAL		$5,902.73