Larson Auto Repair

1939 Christine Manor
Baytown, TX
Phone 832-555-3534

Repair Estimate

Estimate number:	EST-905568
Estimate date:	06/10/2023
Customer:	Kaitlin Jenkins
Phone:	281-555-7931
Insurance claim:	C-1099
Vehicle:	2021 Toyota Camry
VIN:	LT1HDYYL9Z67U3577
License plate:	MEY-028

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,299.05
Left tail lamp assembly	1	$1,450.73
Rear bumper reinforcement	1	$1,212.86
Body labor	41.5 hrs	$2,823.03
Paint and materials		$1,002.95
TOTAL		$7,788.62