Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-308451
Estimate date:	4-3-23
Customer:	Jennifer Boyd
Phone:	832-555-1517
Insurance claim:	C-1116
Vehicle:	2010 Hyundai Elantra
VIN:	PJKAKXVJ1JRGE2229
License plate:	2S J9045

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,177.92
Rear bumper reinforcement	1	$900.57
Rear bumper cover	1	$540.39
Body labor	28.9 hrs	$1,966.82
Paint and materials		$956.06
TOTAL		$5,541.76