Larson Auto Repair

1939 Christine Manor
Baytown, TX
Phone 832-555-3534

Repair Estimate

Estimate number:	EST-876268
Estimate date:	03/04/2025
Customer:	Matthew Perez
Phone:	832-555-9848
Insurance claim:	C-1122
Vehicle:	2010 Chevrolet Malibu
VIN:	GG298TUS3ZP2U7080
License plate:	749-ZKZR

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,414.51
Right tail lamp assembly	1	$1,287.24
Rear body panel	1	$911.17
Body labor	37.6 hrs	$2,555.55
Paint and materials		$879.20
TOTAL		$7,047.67