Koch Collision Center

39117 Tiffany Place
Pearland, TX
Phone 281-555-7824

Repair Estimate

Estimate number:	EST-478146
Estimate date:	9-26-24
Customer:	Bryan Benton
Phone:	713-555-7624
Insurance claim:	C-1150
Vehicle:	2021 Ford F-150
VIN:	FYDTY1KA789JM5496
License plate:	597 ZWE

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$612.76
Right tail lamp assembly	1	$715.65
Rear bumper cover	1	$409.13
Body labor	22.9 hrs	$1,555.30
Paint and materials		$857.96
TOTAL		$4,150.80