Carter Auto Body

48281 Skinner Parkways Apt. 252
Houston, TX
Phone 832-555-7015

Repair Estimate

Estimate number:	EST-354320
Estimate date:	12 Aug 2024
Customer:	Sean Farmer
Phone:	713-555-0159
Insurance claim:	C-1167
Vehicle:	2011 Chevrolet Malibu
VIN:	2A6HY87F6ABEH6337
License plate:	

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$496.02
Hood panel	1	$517.41
Right front door shell	1	$303.07
Body labor	12.1 hrs	$819.69
Paint and materials		$482.16
TOTAL		$2,618.35