Riley Auto Repair

500 Shaw Walk
Pearland, TX
Phone 713-555-8121

Repair Estimate

Estimate number:	EST-606187
Estimate date:	2024-04-10
Customer:	Perry Rodriguez
Phone:	346-555-3453
Insurance claim:	C-1177
Vehicle:	2012 Ford F-150
VIN:	5JMLFXUT0DX3P1894
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,454.42
Front bumper cover	1	$1,012.51
Left front fender	1	$1,378.56
Body labor	45.4 hrs	$3,089.65
Paint and materials		$1,677.85
TOTAL		$8,612.99