Robinson Auto Body

10518 Joshua Oval
Sugar Land, TX
Phone 281-555-9973

Repair Estimate

Estimate number:	EST-904109
Estimate date:	07/01/2024
Customer:	Nicholas Young
Phone:	281-555-9406
Insurance claim:	C-1189
Vehicle:	2012 Chevrolet Malibu
VIN:	DC9JW4VE8DPKU9201
License plate:	CFP 602

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$830.81
Rear bumper cover	1	$589.29
Trunk lid	1	$748.71
Body labor	24.6 hrs	$1,671.54
Paint and materials		$758.17
TOTAL		$4,598.52