Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-174826
Estimate date:	3-3-23
Customer:	Tyler Espinoza
Phone:	713-555-6884
Insurance claim:	C-1204
Vehicle:	2022 Hyundai Elantra
VIN:	S7W6W1DA91R8E1192
License plate:	HQV 527

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,314.40
Left tail lamp assembly	1	$709.70
Rear bumper reinforcement	1	$844.48
Body labor	31.9 hrs	$2,171.12
Paint and materials		$1,019.52
TOTAL		$6,059.22