Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-648333
Estimate date:	11/17/2024
Customer:	Robert Miller
Phone:	832-555-9570
Insurance claim:	C-1273
Vehicle:	2013 Toyota Camry
VIN:	DJBCTA93XJBGT3347
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,786.12
Left quarter panel	1	$1,428.51
Right front door shell	1	$1,267.04
Body labor	48.5 hrs	$3,300.84
Paint and materials		$1,560.70
TOTAL		$9,343.21