Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-700988
Estimate date:	05/16/2023
Customer:	Teresa Martin
Phone:	832-555-8269
Insurance claim:	C-1284
Vehicle:	2017 Chevrolet Malibu
VIN:	EBDZRDDX28SBS6185
License plate:	HNR J10

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,001.93
Rear bumper reinforcement	1	$996.78
Trunk lid	1	$787.13
Body labor	36.4 hrs	$2,477.76
Paint and materials		$1,217.25
TOTAL		$6,480.85