Riley Auto Repair

500 Shaw Walk
Pearland, TX
Phone 713-555-8121

Repair Estimate

Estimate number:	EST-866062
Estimate date:	2024-06-04
Customer:	Ryan Miller
Phone:	832-555-4740
Insurance claim:	C-1306
Vehicle:	2012 Toyota Camry
VIN:	
License plate:	H65 4SQ

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,680.16
Right front door shell	1	$1,366.60
Left quarter panel	1	$816.59
Body labor	37.0 hrs	$2,516.70
Paint and materials		$1,679.38
TOTAL		$8,059.43