Brewer Collision Center

07991 Amanda Parkways Suite 251
Sugar Land, TX
Phone 832-555-4278

Repair Estimate

Estimate number:	EST-177216
Estimate date:	June 6, 2024
Customer:	Peter Lee
Phone:	
Insurance claim:	C-1331
Vehicle:	2023 Hyundai Elantra
VIN:	UX9SB2ZH2APKD6729
License plate:	9U-KXLC

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,242.60
Trunk lid	1	$978.93
Rear bumper reinforcement	1	$1,063.13
Body labor	34.4 hrs	$2,342.23
Paint and materials		$977.49
TOTAL		$6,604.38