Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-539080
Estimate date:	9-5-23
Customer:	Rhonda Miller
Phone:	832-555-0162
Insurance claim:	C-1411
Vehicle:	2015 Ford F-150
VIN:	B1WJFL794XW0U5597
License plate:	40P M83

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$595.31
Right tail lamp assembly	1	$496.12
Rear body panel	1	$376.47
Body labor	16.7 hrs	$1,137.95
Paint and materials		$398.88
TOTAL		$3,004.73