Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-535358
Estimate date:	August 7, 2023
Customer:	Scott Nelson
Phone:	346-555-3536
Insurance claim:	C-1459
Vehicle:	2016 Chevrolet Malibu
VIN:	
License plate:	579H6

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$527.37
Headlamp assembly	1	$366.79
Left quarter panel	1	$292.79
Body labor	9.9 hrs	$676.34
Paint and materials		$318.65
TOTAL		$2,181.94