Warner Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-342334
Estimate date:	28 Mar 2025
Customer:	Michelle Henry
Phone:	713-555-5273
Insurance claim:	C-1476
Vehicle:	2024 Toyota Camry
VIN:	15H9EDMH5FLTT7422
License plate:	PZP 153

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$853.33
Rear body panel	1	$806.10
Rear bumper reinforcement	1	$800.87
Body labor	24.7 hrs	$1,682.50
Paint and materials		$846.30
TOTAL		$4,989.10