# Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-261761 |
| **Estimate date:** | 3-23-25 |
| **Customer:** | Michael King |
| **Phone:** | 713-555-9962 |
| **Insurance claim:** | C-1003 |
| **Vehicle:** | 2024 Jeep Cherokee |
| **VIN:** | ZKYUXB331G74X0521 |
| **License plate:** | 63OD485 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Headlamp assembly | 1 | $1,665.01 |
| Right front door shell | 1 | $1,581.88 |
| Front bumper cover | 1 | $762.97 |
| Body labor | 66.0 hrs | $3,168.66 |
| Paint and materials | | $1,527.00 |
| TOTAL | | $8,705.52 |

### Appraiser remarks

The vehicle presents with a side impact to the driver's door, with the rear quarter panel and sill showing deformation consistent with a side collision at an intersection. Damage pattern lines up with the account given. Repair plan calls for door replacement, quarter panel repair and refinishing, and sill straightening. Labor hours are slightly above typical for this scope and should be reviewed aganist the blending allowance. Parts pricing and paint materials appear in order. Invoices reviewed show no duplicated line items. No prior damage to this vehicle is on record, so the repair scope can be treated as limited to this loss.