Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-172358
Estimate date:	2023-11-28
Customer:	David May
Phone:	832-555-0111
Insurance claim:	C-1009
Vehicle:	2017 Nissan Altima
VIN:	KJDGSZRF00CEP3181
License plate:	170N7

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$243.46
Left quarter panel	1	$220.80
Front bumper cover	1	$217.06
Body labor	6.8 hrs	$465.46
Paint and materials		$244.34
TOTAL		$1,391.12

Appraiser remarks

The rear quarter panel and bumper coevr show crush and tear patterns that line up well with the impact described for a left turn collision. The estimated labor hours match the extnet of the repairs, and the parts list follows the damage as recorded. Two similar charges entered on the same day are under review before approval. Shop records also show comparable major damage on the same panels from an earlier accident that was never reported, and the current claim presents that prior damage as new. Recommend holding payment on the affected items until the prior repair history is verified and the two charges are reconciled. Remaining items can proceed once that review is complete.