Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-666313
Estimate date:	2-15-23
Customer:	Lauren Stevens
Phone:	832-555-0765
Insurance claim:	C-1013
Vehicle:	2023 Nissan Altima
VIN:	2BBG1TNK1M32G7476
License plate:	985-UQX

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,016.93
Right tail lamp assembly	1	$805.83
Rear bumper cover	1	$435.16
Body labor	19.2 hrs	$1,308.91
Paint and materials		$687.30
TOTAL		$4,254.13

Appraiser remarks

The rear bumper cover, trunk lid, and right taillamp assembly show crushing and tearing consistent with the reported rear-end impact, and the pattern of damage lines up with the described collision. Repair labor hours are reasonable for the scope of work outlined. No prior damage to the vehicle has come to light during inspection. Two similar line-item charges entered on the same day are currently being verified against the parts invoices before the estimate is finalized. Repair plan: replace the bumper cover, trunk lid, and taillamp, refinish affected panels, and recheck the rear body alginment after parts are fitted.