Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-328894
Estimate date:	5-28-25
Customer:	Tiffany Bennett
Phone:	281-555-7789
Insurance claim:	C-1018
Vehicle:	2021 Honda Civic
VIN:	GYYFJ8NL4DYJP9508
License plate:	60-17039

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$327.42
Left front fender	1	$262.19
Hood panel	1	$291.60
Body labor	14.0 hrs	$671.36
Paint and materials		$264.42
TOTAL		$1,816.99

Appraiser remarks

Appraiser's remarks: The right rear quarter panel and rear passenger door show scrape marks, a long shallow dent, and paint transfer consistent with a sideswipe during a lane change, and the damage pattern lines up with the impact as described. The repair plan calls for panel straightening, refinishing of the door and quarter panel, and replacement of the damaged mirror housing. Labor hours appear slightly high for this scope and should be reviewed against standard guide times. The shop invoices show no repeated charges. An earlier inspection photo shows a dent in the same location before this incident, so the prior damage should be separated from the current repair scope.