Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-461248
Estimate date:	01/27/2024
Customer:	Nancy Johnson
Phone:	281-555-6134
Insurance claim:	C-1022
Vehicle:	2023 Toyota Camry
VIN:	
License plate:	469-PJK

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,081.78
Hood panel	1	$775.58
Right front door shell	1	$564.56
Body labor	29.8 hrs	$1,431.52
Paint and materials		$990.84
TOTAL		$4,844.28

Appraiser remarks

The vehicle presents with scraping and paint transfer along the right rear quarter panel, a cracked rear bumper cover end, and a dented rear door skin with a broken side marker lens. The pattern of contact is largely consistent with a sideswipe at lane-change speed. Parts and paint materials on the estimate appear in order, and no duplicate line items were found. Labor hours run slightly above typical for this extent of damage, so a review of blend and refinish time is recommended. No prior damage to this vehicle is known from the file. Proceed with repair as scoped once the labor adjustment is confirmed.