Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-895869
Estimate date:	17 Jun 2024
Customer:	Melissa King
Phone:	713-555-4607
Insurance claim:	C-1025
Vehicle:	2010 Hyundai Elantra
VIN:	
License plate:	039F2

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$860.94
Front bumper cover	1	$696.99
Left quarter panel	1	$660.30
Body labor	17.8 hrs	$1,212.94
Paint and materials		$693.57
TOTAL		$4,124.74

Appraiser remarks

The vehicle presents a side impact to the driver's door and rear quarter panel, with deformation concentrated lower on the body than the claimant's account would suggest, and the dents sit on the opposite flank from the reported point of contact. The proposed repair plan covers panel straightening, replacement of the rear door skin, refinishing of adjacent panels for colour match, and recalibration of the door-mounted sensor. Labor hours requested are consistent with the extent of the visible deformation and the parts listed. Shop invoices show a single set of charegs with no repeated line items. Inspection found no indication of prior collision repair or unrelated older damage on the vehicle. The location and height of the dents should be reviewed against the loss description before final approval.