Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-110127
Estimate date:	2025-02-18
Customer:	Brandon Williamson
Phone:	713-555-7342
Insurance claim:	C-1032
Vehicle:	2014 Ford F-150
VIN:	YJHY3RCTXSLJK1527
License plate:	

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$398.97
Left front fender	1	$323.10
Right front door shell	1	$234.43
Body labor	9.2 hrs	$626.26
Paint and materials		$356.45
TOTAL		$1,939.21

Appraiser remarks

The vehicle was inspected at the shop after a sideswipe that occurred during a lane change. The damage runs along the right rear quarter panel and rear bumper cover, with scuffing and a cracked tail light lens, and it lines up well with the impact as reported. The repair plan calls for replacing the bumper cover, refinishing the quarter panel, and replacing the lens. The labor hours requested match the scope of this damage, and the parts list contains no duplicate line items. Nothing in the file points to earlier damage to this vehicle, so the estimate is recommended for approval as submitted.