Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-159000
Estimate date:	2025-06-14
Customer:	James Burton
Phone:	832-555-4818
Insurance claim:	C-1036
Vehicle:	2023 Kia Sorento
VIN:	0PL94M2B268466000
License plate:	6197 NC

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,442.73
Right front door shell	1	$1,287.50
Headlamp assembly	1	$1,016.23
Body labor	33.5 hrs	$2,279.37
Paint and materials		$1,420.99
TOTAL		$7,446.82

Appraiser remarks

The vehicle presented with scraping and paint transfer along the right rear quarter panel, a cracked rear bumper cover at the right corner, and a dented right rear door skin with a damaged mirror housing. The pattern of contact runs along the body in the direction you would expect from a sideswipe during a lane change, and the damage is largely consistent with the impact as described. The repair plan calls for replacing the bumper cover, repairing and refinishing the door and quarter panel, and replacing the mirror housing. The labor hours requested fit the scope of this work. Nothing in the file points to earlier damage on this vehicle, and the invoices reviewed show no duplicate charges for the same parts or labor.