Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-619447
Estimate date:	05/04/2023
Customer:	James Castillo
Phone:	713-555-1851
Insurance claim:	C-1040
Vehicle:	2011 Ford F-150
VIN:	VGL76R1N27NAB8970
License plate:	9G-GMWQ

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,964.83
Left front fender	1	$1,635.78
Hood panel	1	$1,280.62
Body labor	45.3 hrs	$3,081.71
Paint and materials		$1,360.04
TOTAL		$9,322.98

Appraiser remarks

Appraiser's remarks: The rear quarter panel and bumper cover show damage consistent with the impact described by the insured while turning left, and the pattern of deformation lines up with that account. Labor hours on the estimate fit the extent of the damage and the planned repairs, which include panel straightening, replaecment of the bumper cover, and refinishing. No prior damage to this vehicle is known from our records. Two similar charges submitted on the same day are under review before the estimate is finalized.